HISTORIC VIEW and Sansome Streets - 1872 (CAL-1167) Structure

History: View of buildings at corner of California and Sansome Sts., destroyed by fire of 1906. Fireman's Fund Insurance Building at corner. Next to it, to west, California Savings Bank Building and at end of block at Leidesdorff St., appears Merchants Exchange. Bank of California (1866-1867) appears, in part, at lower right corner of photo.

References: Mr. Roy Graves, San Francisco, California. (over)

Form 10-444 (2/62) 9408

State

HISTORIC AMERICAN BUILDINGS SURVEY

| 1995年1月 | 1995年1日 | 19

Prepared by: Joseph A. Baird, Jr., Architectural Hist., San Francisco, California. August 1961